

# NOI Part II: Summary of Receiving Waters, Dedham, MA

Prepared 8/8/2018, based on 2014 integrated list, 201 total outfalls/interconnections

Waterbody	# Outfalls	Impairments
MA72-07 (Charles, Charles River)	138	DDT Escherichia coli Eurasian Water Milfoil, Myriophyllum spicatum Fish-Passage Barrier Fishes Bioassessments Non-Native Aquatic Plants Nutrient/Eutrophication Biological Indicators Other flow regime alterations PCB in Fish Tissue Phosphorus (Total)
MA73-02 (Boston Harbor: Neponset, Neponset River)	14	DDT Debris/Floatables/Trash Escherichia coli Fecal Coliform Foam/Flocs/Scum/Oil Slicks Other Oxygen, Dissolved PCB in Fish Tissue Turbidity
MA73-28 (Boston Harbor: Neponset, Mother Brook)	48	Color DDT Escherichia coli Fecal Coliform Low flow alterations Mercury in Fish Tissue Oxygen, Dissolved PCB in Fish Tissue Phosphorus (Total) Taste and Odor