

NOI Part II: Summary of Receiving Waters, Milton, MA

Prepared 8/8/2018, based on 2014 integrated list, 177 total outfalls/interconnections

Waterbody	# Outfalls	Impairments
MA73-02 (Boston Harbor: Neponset, Neponset River)	21	DDT Debris/Floatables/Trash Escherichia coli Fecal Coliform Foam/Flocs/Scum/Oil Slicks Other Oxygen, Dissolved PCB in Fish Tissue Turbidity
MA73-03 (Boston Harbor: Neponset, Neponset River)	19	DDT Debris/Floatables/Trash Enterococcus Escherichia coli Fecal Coliform Foam/Flocs/Scum/Oil Slicks Other Oxygen, Dissolved PCB in Fish Tissue Polychlorinated biphenyls
MA73-04 (Boston Harbor: Neponset, Neponset River)	15	Debris/Floatables/Trash Enterococcus Fecal Coliform Other Oxygen, Dissolved PCB in Fish Tissue Turbidity

NOI Part II: Summary of Receiving Waters, Milton, MA

Prepared 8/8/2018, based on 2014 integrated list, 177 total outfalls/interconnections

Waterbody	# Outfalls	Impairments
MA73-26 (Boston Harbor: Neponset, Unquity Brook)	18	Debris/Floatables/Trash Escherichia coli Fecal Coliform Low flow alterations Oxygen, Dissolved pH, Low Phosphorus (Total) Physical substrate habitat alterations Sedimentation/Siltation
MA73-29 (Boston Harbor: Neponset, Pine Tree Brook)	92	Aquatic Plants (Macrophytes) Escherichia coli Fecal Coliform Oxygen, Dissolved Physical substrate habitat alterations Turbidity
MA73003 (Boston Harbor: Neponset, Russell Pond)	5	Non-Native Aquatic Plants Turbidity
MA73059 (Boston Harbor: Neponset, Turners Pond)	2	Nutrient/Eutrophication Biological Indicators Oxygen, Dissolved Turbidity
MA74-10 (Boston Harbor: Weymouth & Weir, Furnace Brook)	4	Oxygen, Dissolved